

EAST WINDSOR, CONNECTICUT

BROAD BROOK MILL POND DAM  
CT-00271

The original hardcopy version of this report  
contains color photographs and/or drawings.  
For additional information on this report  
please email

NATIONAL DAM INSPECTION PROGRAM  
CORPS OF ENGINEERS

U.S. Army Corps of Engineers  
New England District  
Email: [Library@nae02.usace.army.mil](mailto:Library@nae02.usace.army.mil)

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER CT 00271	2. GOVT ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Broad Brook Mill Pond Dam		5. TYPE OF REPORT & PERIOD COVERED INSPECTION REPORT
NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS		6. PERFORMING ORG. REPORT NUMBER
7. AUTHOR(s) U.S. ARMY CORPS OF ENGINEERS NEW ENGLAND DIVISION		8. CONTRACT OR GRANT NUMBER(s)
9. PERFORMING ORGANIZATION NAME AND ADDRESS		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
11. CONTROLLING OFFICE NAME AND ADDRESS DEPT. OF THE ARMY, CORPS OF ENGINEERS NEW ENGLAND DIVISION, NEDED 424 TRAPELO ROAD, WALTHAM, MA. 02254		12. REPORT DATE March 1980
		13. NUMBER OF PAGES 50
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office)		15. SECURITY CLASS. (of this report) UNCLASSIFIED
		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
16. DISTRIBUTION STATEMENT (of this Report) APPROVAL FOR PUBLIC RELEASE: DISTRIBUTION UNLIMITED		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		
18. SUPPLEMENTARY NOTES Cover program reads: Phase I Inspection Report, National Dam Inspection Program; however, the official title of the program is: National Program for Inspection of Non-Federal Dams; use cover date for date of report.		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) DAMS, INSPECTION, DAM SAFETY, East Windsor, Conn.		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) The dam is a 15 ft. high stone masonry, gravity structure, probably on bedrock for its entire length. The project is approx. 193 ft. in length, consisting of an 81 ft. 10 masonry spillway section, a 32 ft. long masonry and earthfill section to the left of the spillway. Based upon visual inspection, the project is in poor condition.		

The dam is a 15 foot high stone masonry, gravity structure, probably founded on bedrock for its entire length. The project is approximately 193 feet in length, consisting of an 81 foot long masonry spillway section, a 32 foot long masonry and earthfill section to the left of the spillway, and an 80 foot long stone masonry and earthfill dike extending upstream from the spillway along the right side of the impoundment. Two wood sluice gates, controlling flow to a downstream factory, are located at the left end of the dam. A single span highway bridge along Connecticut Route 191 crosses the stream approximately 50 feet downstream of the dam.

The spillway, with an overflow length of 77 feet, is a broad-crested masonry weir of trapezoidal cross-section, with a permanently attached timber crest and breakaway flashboards. The spillway is separated into two sections by a stone masonry pier which houses an inoperable low level outlet. The spillway approach channel is shallow and rocky. The downstream face of the spillway is vertical, with the natural bedrock stream channel functioning as a splash apron.

For the Owner's information and use, the following items are attached:

1. "Visual Inspection Check List".
2. Hydraulic/Hydrologic computations.
3. Existing data and correspondence
4. Photos of project.

Based upon visual inspection, the project is in poor condition. The following features could influence the future condition and/or stability of the project.

1. Areas of the upstream and downstream masonry faces of the dam and sluice gate channel are deteriorated. This deterioration includes missing or cracked mortar, and weathered or displaced stone blocks.
2. There is a seep of approximately 4 to 6 gallons per minute near the left end of the dam.
3. The low-level outlet is inoperable.
4. The upstream slope of the dike is eroded.

The Owner should retain the services of a registered professional engineer to perform further studies pertaining to the following general recommendations. More specific recommendations made by the engineer should be implemented by the owner.

1. The areas of deteriorated masonry on the upstream and downstream faces of the dam, as well as the sluice gate intake and outlet channels should be investigated, analyzed and repaired.
2. Seepage through the dam should be investigated. Measures should be undertaken to eliminate the seepage, or a seepage monitoring program should be established.
3. The low-level outlet should be made operable or a new one installed in order to draw down the pond level, should the need occur.
4. The eroded areas of the upstream slope of the dike should be filled with selected soil, graded and protected from future erosion.

# INSPECTION CHECK LIST

## PARTY ORGANIZATION

PROJECT Broad Brook Reservoir Dam DATE: March 24, 1980

TIME: 10:00 am - 12:00 noon

WEATHER: Sunny, 45° F

W.S. ELEV. 85.0 ± U.S. \_\_\_\_\_ DN.S

### PARTY:

### INITIALS:

### DISCIPLINE:

1. <u>Peter M. Heynen</u>	<u>PMH</u>	<u>Project Manager</u>
2. <u>MIRON Petrovsky</u>	<u>MP</u>	<u>Sr. Geotech. Engr.</u>
3. <u>Theodore Stevens</u>	<u>TS</u>	<u>Project Engineer</u>
4. <u>Hector Moreno</u>	<u>HM</u>	<u>Chief Hydraulic Engr.</u>
5. <u>Moshe Norman</u>	<u>MN</u>	<u>Survey</u>
6. _____	_____	_____

### PROJECT FEATURE

### INSPECTED BY

### REMARKS

1. <u>Earthfill Masonry Section</u>	<u>PMH, MP, TS, HM, MN</u>	
2. <u>Masonry Dike</u>	<u>Same</u>	
3. <u>Intake Structure</u>	<u>Same</u>	
4. <u>Outlet Structure</u>	<u>Same</u>	
5. <u>Low-Level Outlet</u>	<u>Same</u>	
6. <u>Masonry Spillway</u>	<u>Same</u>	
7. <u>Gate Structure</u>	<u>Same</u>	
8. _____		
9. _____		
10. _____		
11. _____		
12. _____		

## PERIODIC INSPECTION CHECK LIST

Page A-2PROJECT Broad Brook Reservoir DamDATE March 24, 1980PROJECT FEATURE Earthfill Masonry Section BY PMH,MP,TS,HM,MN

AREA EVALUATED	CONDITION
<u>DAM EMBANKMENT</u>	
Crest Elevation	88.6 ±
Current Pool Elevation	85.0 ±
Maximum Impoundment to Date	Unknown
Surface Cracks	Some, masonry and joints
Pavement Condition	N/A
Movement or Settlement of Crest	Irregular earthfill top
Lateral Movement	None observed
Vertical Alignment	} Appears good
Horizontal Alignment	
Condition at Abutment and at Concrete Structures	Good
Indications of Movement of Structural Items on Slopes	None observed
Trespassing on Slopes	N/A
Sloughing or Erosion of Slopes or Abutments	Erosion & cracking on d/s slope
Rock Slope Protection-Riprap Failures	Eroded masonry of u/s wall
Unusual Movement or Cracking at or Near Toes	None observed
Unusual Embankment or Downstream Seepage	Seep on d/s slope near toe w/rate approx. 4-6 gpm
Piping or Boils	None observed
Foundation Drainage Features	N/A
Toe Drains	12" high-level tile drain clogged by wood
Instrumentation System	N/A

## PERIODIC INSPECTION CHECK LIST

Page A-3PROJECT Broad Brook Reservoir DamDATE March 24, 1980PROJECT FEATURE Masonry DikeBY PMH, MP, TS, HM, MN

AREA EVALUATED	CONDITION
<u>DIKE EMBANKMENT</u>	
Crest Elevation	89.4±
Current Pool Elevation	85.4±
Maximum Impoundment to Date	Unknown
Surface Cracks	Some, in masonry
Pavement Condition	Fair, top of masonry wall
Movement or Settlement of Crest	} None observed
Lateral Movement	
Vertical Alignment	} Appears good
Horizontal Alignment	
Condition at Abutment and at Concrete Structures	Good
Indications of Movement of Structural Items on Slopes	None observed
Sloughing or Erosion of Slopes or Abutments	Eroded earthfill slopes
Rock Slope Protection-Riprap Failures	N/A
Unusual Movement or Cracking at or Near Toes	} None observed
Unusual Embankment or Downstream Seepage	
Piping or Boils	} N/A
Foundation Drainage Features	
Toe Drains	} N/A
Instrumentation System	
Trespassing on Slopes	Some

# PERIODIC INSPECTION CHECK LIST

Page A-4

PROJECT Broad Brook Reservoir Dam

DATE March 24, 1980

PROJECT FEATURE Intake Structure

BY PMH, NPTS, HM, MN

AREA EVALUATED		CONDITION
<p><u>OUTLET WORKS-INTAKE CHANNEL AND INTAKE STRUCTURE</u></p> <p>a) <u>Approach Channel</u></p> <p>Slope Conditions</p> <p>Bottom Conditions</p> <p>Rock Slides or Falls</p> <p>Log Boom</p> <p>Debris</p> <p>Condition of Concrete Lining</p> <p>Drains or Weep Holes</p> <p>b) <u>Intake Structure</u></p> <p>Condition of Concrete</p> <p>Stop Logs and Slots</p>		
		<p>Masonry w/concrete lining</p> <p>Eroded masonry</p> <p>Not observed</p> <p>None observed</p> <p>Good</p> <p>Floating leaves &amp; wood</p> <p>fair, some cracking</p> <p>N/A</p> <p>N/A</p>



# PERIODIC INSPECTION CHECK LIST

Page A-5

PROJECT Broad Brook Reservoir Dam

DATE March 24, 1980

PROJECT FEATURE Gate Structure

BY PMH, MP, TS, HM, MN

AREA EVALUATED	CONDITION
<u>OUTLET WORKS-CONTROL TOWER</u>	
a) <u>Concrete and Structural</u>	
General Condition	<i>Fair</i>
Condition of Joints	<i>Fair, Masonry joints</i>
Spalling	<i>Same</i>
Visible Reinforcing	} <i>N/A</i>
Rusting or Staining of Concrete	
Any Seepage or Efflorescence	
Joint Alignment	
Unusual Seepage or Leaks in Gate Chamber	<i>None observed</i>
Cracks	<i>Some</i>
Rusting or Corrosion of Steel	<i>N/A</i>
b) <u>Mechanical and Electrical</u>	
Air Vents	} <i>N/A</i>
Float Wells	
Crane Hoist	
Elevator	
Hydraulic System	<i>Two 2' x 7.5' wooden sluice gates, operable</i>
Service Gates	
Emergency Gates	
Lightning Protection System	} <i>N/A</i>
Emergency Power System	
Wiring and Lighting System	

## PERIODIC INSPECTION CHECK LIST

Page A-6PROJECT Broad Brook Reservoir DamDATE March 24, 1980PROJECT FEATURE Outlet StructureBY PMH, MP, TS, HM, MN

AREA EVALUATED	CONDITION
<u>OUTLET WORKS-OUTLET STRUCTURE AND OUTLET CHANNEL</u>	<i>Masonry w/ concrete lining</i>
General Condition of Concrete	<i>Fair</i>
Rust or Staining	<i>N/A</i>
Spalling	<i>Some cracking</i>
Erosion or Cavitation	<i>None observed</i>
Visible Reinforcing	<i>N/A</i>
Any Seepage or Efflorescence	<i>3 seeps on d/s overflow side w/flow approx. 16-20 gpm</i>
Condition at Joints	<i>N/A</i>
Drain Holes	<i>N/A</i>
Channel	<i>N/A</i>
Loose Rock or Trees Overhanging Channel	<i>N/A</i>
Condition of Discharge Channel	<i>Eroded d/s masonry of overflow side.</i>

## PERIODIC INSPECTION CHECK LIST

Page A-7PROJECT Broad Brook Reservoir DamDATE March 24, 1980PROJECT FEATURE Masonry SpillwayBY PMH, MP, TS, HM, MN

AREA EVALUATED	CONDITION
<u>OUTLET WORKS-SPILLWAY WEIR, APPROACH AND DISCHARGE CHANNELS</u>	
a) <u>Approach Channel</u>	
General Condition	Good
Loose Rock Overhanging Channel	N/A
Trees Overhanging Channel	
Floor of Approach Channel	Not observed
b) <u>Weir and Training Walls</u>	
General Condition of Concrete	Fair
Rust or Staining	N/A
Spalling	Deteriorated masonry on d/s slope
Any Visible Reinforcing	N/A
Any Seepage or Efflorescence	seeps & wet joints on right side of d/s slope w/flow = 1-2 gpm.
Drain Holes	N/A
c) <u>Discharge Channel</u>	
General Condition	Fair
Loose Rock Overhanging Channel	None observed
Trees Overhanging Channel	
Floor of Channel	Bedrock
Other Obstructions	Boulders, stones and masonry blocks at central and left portions of spillway apron

# PERIODIC INSPECTION CHECK LIST

Page A-8

PROJECT Broad Brook Reservoir Dam

DATE March 24, 1980

PROJECT FEATURE Low-Level Outlet

BY PMH, MP, TS, HM, MN

AREA EVALUATED	CONDITION
<u>OUTLET WORKS-CONTROL TOWER</u>	
a) <u>Concrete and Structural</u>	
General Condition	Old outlet at base of center masonry pier approx. 3'x3'
Condition of Joints	
Spalling	
Visible Reinforcing	
Rusting or Staining of Concrete	
Any Seepage or Efflorescence	
Joint Alignment	
Unusual Seepage or Leaks in Gate Chamber	
Cracks	
Rusting or Corrosion of Steel	
b) <u>Mechanical and Electrical</u>	
Air Vents	N/A
Float Wells	
Crane Hoist	
Elevator	
Hydraulic System	
Service Gates	Not observed
Emergency Gates	
Lightning Protection System	N/A
Emergency Power System	
Wiring and Lighting System	

Project INSPECTION OF NON-FEDERAL DAMS IN NEW ENGLAND Sheet D-1 of 10  
 Computed By WJ Checked By GAP Date 4/3/80  
 Field Book Ref. \_\_\_\_\_ Other Refs. CE # 27-785-HA Revisions \_\_\_\_\_

### HYDROLOGIC / HYDRAULIC INSPECTION

#### BROAD BROOK MILL POND DAM, EAST WINDSOR, CT.

#### 1) PERFORMANCE AT PEAK FLOOD CONDITIONS:

##### 1) PROPOSED MAXIMUM FLOOD (PMF):

a) WATERSHED CLASSIFIED AS "FLAT" TO "ROLLING"

b) WATERSHED AREA:  $DA = 13.6 \text{ mi}^2$

(C.F. MEASURE - NOTE: CONN. DEP. BULLETIN N°1, 1970 (EXAMINATION OF NATURAL DRAINAGE AREAS) P. 26 SHOWS  $DA = 14.6 \text{ sq. mi.}$  HOWEVER, THIS MEASURE DOES NOT CORRELATE WITH D.A. TO USGS GAGING STA. 18449)

c) PEAK FLOODS (FROM NED-ACE GUIDELINES - GUIDE CURVES FOR PMF):

i) FROM GUIDE CURVES,  $CSM = 1200 \text{ cfs/mi}^2$

ii)  $PMF \approx 1200 \times 13.6 = 16300 \text{ cfs}$

iii)  $1/2 \text{ PMF} = 8150 \text{ SAY, } 8100 \text{ cfs}$

#### 2) SURCHARGE AT PEAK INFLOWS (PMF AND $1/2 \text{ PMF}$ )

##### a) OUTFLOW RATING CURVE

##### i) SPILLWAY AND OVERFLOW PROFILE FOR SURCHARGES OVERTOPPING THE DAM

2- SPILLWAY SECTIONS, BOTH WITH FLASH BOARDS (RIGHT SPILLWAY FLASHBOARD IS COLLAPSED) ABOVE PERMANENT WOODEN SILL (PLATFORM) ATOP MASONRY. FLASHBOARDS DESIGNED TO FAIL AT (+) 2' HEAD (SEE MACCI ENGRS. LETTER OF MAY 3, 1976). CENTRAL PIER ASSUMED TO BE (+) AT SAME ELEV. AS ATOP OF FLASHBOARDS (SEE OVERFLOW PROFILE P. D-2).

Project NON-FEDERAL DAMS INSPECTION

Sheet D-2 of 10

Computed By HMM

Checked By GA12

Date 4/3/80


Field Book Ref. \_\_\_\_\_

Other Refs. CE # 27-785-HA

Revisions \_\_\_\_\_

THEREFORE, ASSUME  $C=3.3$  FOR SPILLWAY FLOW, EITHER OVER THE FLASHBOARDS OR OVER THE WOODEN CREST REMAINING AFTER COLLAPSE OF THE FLASHBOARDS. ASSUME  $C=3.0$  FOR TOP OF DAM AND OTHER OVERFLOWS.


ASSUME FLASHBOARDS IN PLACE FOR OVERFLOW CURVE DEVELOPMENT, FOR HEADS UP TO 2'.



BROAD BROOK HILL POND DAM  
APPROXIMATE OVERFLOW PROFILE

NOTE: DATA FROM C.E. OBSERVATIONS  
ON 4/1/80 BY HMM & R.J.

\*SEE NOTE ON P. D-4



(U) THEREFORE, ASSUMING EQUIVALENT LENGTHS FOR THE SLOPING TERRAIN, THE OVERFLOW CURVE CAN BE APPROXIMATED AS FOLLOWS:

$$1) \text{ STREET } Q_{ST} = 3.0 \times 43 \times (H - 3.6)^{3/2} = 129 (H - 3.6)^{3/2}$$

NOTE: FLASHBOARDS TOP (CREST) ELEV. 86' NGVD ASSUMED AS DATUM.

Project NON-FEDERAL DAMS INSPECTION Sheet D-3 of 10  
 Computed By QW Checked By GAB Date 4/2/80  
 Field Book Ref. \_\_\_\_\_ Other Refs. CE# 27-785-HA Revisions \_\_\_\_\_

2') TOP OF DAM & ADJACENT TERRAIN AT ASSUMED ELEV. 89' NGVD:

$$Q_3 = 3.0 \times 115 \times (H-3)^{3/2} = \underline{\underline{345 (H-3)^{3/2}}}$$

3') SPILLWAY SECTIONS

a.) WITH FLASHBOARDS:

$$Q_{s1} = 3.3 \times 77 \times H^{3/2} + 3 \times 4 \times H^{3/2} = \underline{\underline{266 H^{3/2}}} \quad (H \leq 2')$$

b.) W/O FLASHBOARDS:

$$Q_{s2} = \underline{\underline{254 (H+1.5)^{3/2}}} + 12 H^{3/2} \quad (H > 2')$$

4') SLOPING TERRAIN (RIGHT)

$$(Q_R')_1 = \frac{2}{3} \times 50 \times 3 \times (H-3)^{5/2} = \underline{\underline{100 (H-3)^{5/2}}} \quad H \leq 4'$$

$$(Q_R')_1 = 3 \times 50 \times (H-3.23)^{3/2} = \underline{\underline{150 (H-3.23)^{3/2}}} \quad H > 4'$$

5') TERRAIN (RIGHT) ASSUMED AT ELEV. 90' NGVD

$$Q_{R2} = 3 \times 80 \times (H-4)^{3/2} = \underline{\underline{240 (H-4)^{3/2}}}$$

6') SLOPING TERRAIN ABOVE ELEV. 90' NGVD (RIGHT)

$$Q_{R3} = \frac{2}{3} \times 5 \times 3 \times (H-4)^{5/2} = \underline{\underline{10 (H-4)^{5/2}}}$$

THEREFORE, THE TOTAL OUTFLOW IS APPROXIMATED BY:

$$Q = Q_{s1} + Q_3 + Q_{s2} + (Q_R')_* + Q_{R2} + Q_{R3}$$

WHERE THE (\*) REPLACES THE SUBINDEX OF THE APPLICABLE FORMULAE ON (3') AND (4') ABOVE.

Project NON-FEDERAL DAMS INSPECTION

Sheet D-4 of 10

Computed By YLD

Checked By GAB


Date 4/4/80

Field Book Ref. \_\_\_\_\_

Other Refs. CE # 27-785-HA

Revisions \_\_\_\_\_

### (ii) BROAD BROOK MILL POND DAM - OUTFLOW RATING CURVE



\*NOTE: W/S ELEV. 86' ON THE BROAD BROOK, CT. QUADRANGLE SHEET (REV. 1972) IS ASSUMED TO BE THE FLASHBOARDS TOP ELEVATION (NORMAL POOL) ON NATIONAL GEODETIC VERTICAL DATUM (NGVD).



Project NON-FEDERAL DAMS INSPECTION Sheet D-5 of 10  
 Computed By YH Checked By GRB Date 4/4/80  
 Field Book Ref. \_\_\_\_\_ Other Refs. CE #27-785-HA Revisions \_\_\_\_\_

### b) SURCHARGE HEIGHT TO PASS PEAK INFLOWS ( $Q_p$ & $Q'_p$ )

i) @  $Q_p = PMF \approx 16300 \text{ cfs}$   $H_s \approx \underline{7.9'}$

ii) @  $Q'_p = \frac{1}{2} PMF \approx 8100 \text{ cfs}$   $H'_s \approx \underline{5.7'}$

### c) EFFECT OF SURCHARGE STORAGE - PEAK OUTFLOWS:

#### i) AVE LAKE AREA WITHIN EXPECTED SURCHARGE ( $\bar{A}$ ):

1) LAKE AREA AT FLOW LINE (Elev. 86' NGVD):  $*A_{NL} \approx 18 \text{ ac}$

2) AREA AT CONTOUR 90' NGVD (MSL)\*  $A_{90} = 52 \text{ ac}$

3) AREA AT CONTOUR 100' NGVD (MSL)\*  $A_{100} = 107 \text{ ac}$

$\therefore$  AREA AT ELEV. 94' NGVD (MAX. EXPECTED SURCH):  $A_{94} \approx 75 \text{ ac}$

$\therefore$  AVE. AREA WITHIN EXPECTED SURCHARGE:  $\bar{A} \approx 52 \text{ ac} (= A_{90})$

\*NOTE: AREAS FROM USGS BROAD BROOK, CT. QUAD. SHEET (SCALE 1"=2000') AND GRAPHICAL INTERPOLATION.

#### ii) ASSUME NORMAL POOL AT FLOW LINE (ELEV. 86' NGVD)

iii) WATERSHED D.A.  $\approx 13.6 \text{ sq mi}$  (SEE P. D. 1)

#### iv) PEAK OUTFLOWS ( $Q_p$ & $Q'_p$ )

(DETERMINED ON THE OUTFLOW RATING CURVE P. D. A BY USING THE APPROX. ROUTING: NED-ACE GUIDELINES "SURCHARGE STORAGE ROUTING" ALTERNATE METHOD AND 19' MAX. PROBABLE R.O. IN NEW ENGLAND)

$Q_p \approx 15800 \text{ cfs}$   $H_s \approx 7.8'$

$Q'_p \approx 7800 \text{ cfs}$   $H'_s \approx 5.6'$

Project NON-FEDERAL DAMS INSPECTION Sheet D-6 of 10  
 Computed By YLL Checked By GGP Date 4/7/80  
 Field Book Ref. \_\_\_\_\_ Other Refs. CE #27-785-HA Revisions \_\_\_\_\_

### 3) SPILLWAY CAPACITY RATIO TO PEAK INFLOWS AND OUTFLOWS

SPILLWAY CAPACITY TO:	SURCH.* H (FT)	W.S. ELEV. (FT-NGVD)	SPILLWAY CAPACITY (CFS)	SPILLWAY CAPACITY AS % OF INFLOWS AND OUTFLOWS			
				Q <sub>P1</sub> (16300 CFS)	Q <sub>P1</sub> (8100 CFS)	Q <sub>P2</sub> (15800 CFS)	Q <sub>P2</sub> (7800 CFS)
TOP OF DAM	3	89	2500	15	31	16	32
1/2 PAF	5.6	91.6	5000	—	62	—	64
PAF	7.8	93.8	7500	46	—	47	—

\*SURCHARGE ABOVE TOP OF FLASHBOARDS (ELEV. 86' NGVD)

Project NON-FEDERAL DAMS INSPECTION Sheet D-7 of 10  
Computed By WJL Checked By GAB Date 4/7/80  
Field Book Ref. \_\_\_\_\_ Other Refs. CE #27-785-HA Revisions \_\_\_\_\_

## BROAD BROOK MILL POND DAM

### II) DOWNSTREAM FAILURE HAZARD

#### 1) POTENTIAL IMPACT AREA

EXCEPT FOR ONE HOUSE (±) 2500'  $\downarrow$ S FROM THE DAM WITH FIRST FLOOR (±) 6' ABOVE THE STREAMBED, THE STRUCTURES ALONG BROAD BROOK TO THE SCANTIC RIVER (BOTH ON FURAC - UNDEVELOPED LAND) ARE 11' OR MORE ABOVE THE BROOK CHANNEL.

#### 2) FAILURE AT BROAD BROOK MILL POND DAM:

ASSUME SURCHARGE TO TOP OF DAM (ELEV. 84' NGVD)

a) HEIGHT OF DAM\*:  $H_s = 15'$

b) MID-HEIGHT LENGTH\*:  $L_s = 115'$

c) BREACH WIDTH (SEE NED-ACE  $\frac{1}{2}$  DAM FAILURE GUIDELINES)

$$W = 0.8 \times 115 = 46'$$

$$\text{ASSUME } W_b = \underline{46'}$$

BECAUSE THE LONGEST ABUTMENT TO MID-HEIGHT IS (±) 15' THE ASSUMED BREACH WILL OVERLAP A MIN. OF 30' OF SPILLWAY SECTION.

d) ASSUMED WATER DEPTH (HEAD) AT TIME OF FAILURE:  $H_o = \underline{15'}$

e) SPILLWAY DISCHARGE AT TIME OF FAILURE:

i) PREVIOUS TO FAILURE  $Q_s = 2500 \text{ cfs}$  (SEE P. D-6)

ii) AFTER FAIL. REMAIN. SPWY/PIER (± 51'):  $Q_s' = 1000 \text{ cfs}$

\*FROM C.E. MEASUREMENTS ON 4/1/80 BY WJL & R.J.

Project NON-FEDERAL DAMS INSPECTION Sheet D-8 of 10  
 Computed By YH Checked By GAM Date 4/27/20  
 Field Book Ref. \_\_\_\_\_ Other Refs. CE #27-785-HA Revisions \_\_\_\_\_

f) BREACH OUTFLOW (SEE NED-ACE GUIDELINES)

$$Q_b \approx \frac{8}{27} W_b \sqrt{g} y_o^{3/2} = 4500 \text{ cfs}$$

g) PEAK FAILURE OUTFLOW ( $Q_p$ ) TO BROAD BROOK:

$$Q_p = Q_s' + Q_b \approx \underline{\underline{5500 \text{ cfs}}}$$

3) FLOOD DEPTH\* IMMEDIATELY  $\frac{1}{2}$  FROM DAM:

$$y \approx 0.44 y_o = 6.6' \text{ SAY, } y \approx \underline{\underline{7'}}$$

(\* FROM RETREATING WAVE THEORY APPLIED TO DAM FAILURE)

a) ESTIMATE OF  $\frac{1}{2}$  FAILURE CONDITIONS AT POTENTIAL IMPACT AREA:

(SEE NED-ACE GUIDELINES FOR ESTIMATING  $\frac{1}{2}$  FAILURE HYDROGRAPHS)

a) THE ( $\pm$ ) 2500' LONG REACH OF BROAD BROOK FROM THE DAM TO THE POTENTIAL IMPACT AREA IS GENERALLY TRAPEZOIDAL IN CROSS SECTION WITH ( $\pm$ ) 100' BASE AND ( $\pm$ ) 5" AND ( $\pm$ ) 6" TO 1" SIDE SLOPES. THE AVERAGE REACH SLOPE IS ( $\pm$ ) 0.6%.

b) RESERVOIR STORAGE AT TIME OF FAILURE:

$$* S_{MAX} \approx \underline{\underline{130 \text{ AC-FT}}} \quad (\frac{1}{2} S = 65 \text{ AC-FT})$$

\* STORAGE FROM U.S. ACE INVENTORY OF DAMS DATED 1/23/80, p.31:  $S_{MAX} = 127 \text{ AC-FT}$   
 C.E. ESTIMATE BASED ON AN AVE (MAX.) DEPTH OF ( $\pm$ ) 7':  $S = 126 \text{ AC-FT}$ .  
 ALSO, ESTIMATED BY  $S = .5AH$ ,  $S = 135 \text{ AC-FT}$ . SO, USE  $S_{MAX} = 130 \text{ AC-FT}$ .

c) APPROXIMATE STAGE AT POTENTIAL IMPACT AREA AFTER FAILURE

$$Q_p = 5500 \text{ cfs} \therefore y_1 \approx 6.2', V_1 \approx 47 \text{ AC-FT} \frac{S}{2} \approx \text{ (ON REACH OF 2500'; } \eta_2 = 0.050 \text{)}$$

Project NON-FEDERAL DAM INSPECTION Sheet D-9 of 10  
 Computed By HUL Checked By GRB Date 4/7/80  
 Field Book Ref. \_\_\_\_\_ Other Refs. CE #27-785-HA Revisions \_\_\_\_\_

$$\therefore Q_2 = 3400 \text{ cfs} ; y_2 = 4.7' ; V_2 = 34 ; \bar{V} = 41 \therefore Q_3 = 3700 \text{ cfs}$$

$$\therefore \text{REACH OUTFLOW: } Q_3 = \underline{\underline{3700 \text{ cfs}}} \quad y_3 = \underline{\underline{5'}}$$

$$d) \text{ APPROXIMATE STAGE BEFORE FAILURE: } Q_3 = \underline{\underline{2500 \text{ cfs}}} \quad y_{s2} = \underline{\underline{4'}}$$

$$e) \text{ RAISE IN STAGE AT IMPACT AREA: } \Delta y = \underline{\underline{1'}}$$

### III) SELECTION OF TEST FLOOD

#### 1) CLASSIFICATION OF DAM ACCORDING TO NED-ACE GUIDELINES

$$a) \text{ SIZE: } * \text{STORAGE (MM)} \approx 130 \text{ ACFT} \quad (50 < S < 1000 \text{ ACFT})$$

$$\text{HEIGHT} \approx 15' \quad (H < 25')$$

\* STORAGE: SEE P. D-8 ; HEIGHT: SEE P. D-7

$\therefore$  SIZE CLASSIFICATION: SMALL

b) HAZARD POTENTIAL: AS A RESULT OF THE P/F FAILURE ANALYSIS AND IN VIEW OF THE IMPACT THAT FAILURE OF BROAD BROOK MILL POND DAM MAY HAVE ON THE POTENTIAL IMPACT AREA (P D-7), THE DAM IS CLASSIFIED AS HAVING:

HAZARD CLASSIFICATION: LOW

2) TEST FLOOD: 50 TO 100-YR FREQ. FLOOD.

NOTE: ALTHOUGH IT HAS NOT BEEN ESTIMATED THE 100-YR FREQ. FLOOD IS ASSUMED TO BE OF THE ORDER OF MAGNITUDE OF  $Q_{100} \approx 4000 \text{ cfs}$ . THIS ASSUMPTION SEEMS IN AGREEMENT WITH ESTIMATES IN PREVIOUS STUDIES.

Project NON-FEDERAL DAMS INSPECTION Sheet D-10 of 10  
 Computed By WJN Checked By GRD Date 4/7/80  
 Field Book Ref. \_\_\_\_\_ Other Refs. CE # 27-985-11A Revisions \_\_\_\_\_

At  $Q_{100} = 4000 \text{ cfs}$ , THE DAM WILL BE OVERTOPPED BY (±) 0.9' TO 1.3' ( $Q_R = 3800 \text{ cfs}$ ) OR TO A SURCHARGE OF (±) 3.9' ABOVE NORMAL POOL ELEV. 86' NGVD (TOP OF FLASHBOARDS). (SEE P. D-4.) THE SPILLWAY CAPACITY IS THEREFORE (±) 83% OF THE TEST FLOOD AND (±) 87% OF THE TEST FLOOD PEAK OUTFLOW.

BROAD BROOK MILL POND DAM

Existing Plan

"Proposed Reconstruction"  
Broad Brook Mill Pond Dam  
East Windsor, Conn.  
A. R. Lombardi Associates, Inc.  
August 20, 1979  
1 Sheet

SUMMARY OF DATA AND CORRESPONDENCE

<u>DATE</u>	<u>TO</u>	<u>FROM</u>	<u>SUBJECT</u>	<u>PAGE</u>
-	File	State Board for the Supervision of Dams	Inventory Data	B-3
Dec. 19, 1955	State Board for the Supervision of Dams	Henry W. Buck Buck & Buck Engineers	Request for inspection of dam	B-4
Jan. 12, 1956	William S. Wise Chairman, State Water Commission	Benjamin H. Palmer Member, State Board for the Supervision of Dams	Inspection Report	B-5
June 22, 1956	State Board	John J. Mozzochi, Engineer	Application for construction permit, sketch of dam, computations, and specifications for repairs to dam	B-7
June 29, 1956	John J. Mozzochi	Benjamin H. Palmer	Preliminary Construction permit	B-12
Dec. 3, 1956	William S. Wise	Benjamin H. Palmer	Certificate of Approval	B-13
March 20, 1963	A. J. Macchi	Emitt A. Dell Field Inspector	Request for inspection of dam	B-14
April 18, 1963	Water Resources Commission	A. J. Macchi, Engineers	Revision of flashboard design	B-15
June 1, 1966	Water Resources Commission	John L. Daly, Jr. First Selectman Town of East Windsor	Request for report on condition of dam	B-17



<u>DATE</u>	<u>TO</u>	<u>FROM</u>	<u>SUBJECT</u>	<u>PAGE</u>
June 22, 1966	William Sander Water Resources Commission	A.J. Macchi, Engineers	Inspection Report	B-18
March 29, 1976	Edward Hastillo First Selectman Town of East Windsor	Richard Ryan Plant Engineer Hamilton Standard	Damages due to breaking away of flashboards	B-19
April 12, 1976	A. J. Macchi	Victor F. Galgowski Supt. of Dam Maintenance	Request for inspection of Dam	B-20
May 4, 1976	Victor F. Galgowski	A. J. Macchi	Inspection Report with revised Mozzochi sketch of 6-22-56	B-21

CT-271

STATE BOARD FOR THE SUPERVISION OF DAMS  
INVENTORY DATANAME OF DAM OR POND BROAD BROOK MILL PONDCODE NO. EW (S.C. B.I.O.)

## LOCATION OF STRUCTURE:

Town EAST WINDSOR.Name of Stream BROAD BROOKU.S.G.S. Quad. B. Brook Long 72-52.7 Lat 41-55.0

## OWNER:

Address

HAMILTON STANBROOK CO. OWNERSHIP TO BE  
11 RYE ST. BROOKBROOK 06016 TOWN OF EAST WINDSOR OR 12/78  
633-8375 DA = 77.65M

Telephone

THIS DAM HAS BEEN A SOURCE OF TROUBLE  
QUITE APPARENT THAT SPILLWAY IS INADEQUATEPond Used For: ORIGINALLY FOR PROPOSED WHARF (LIVESTOCK)Dimensions of Pond: Width 500 Length 2,000' Area 25. ADepth of Water below Spillway Level (Downstream) 12' 10'Total Length of Dam 30 Length of Spillway 80'Height of Abutments above Spillway 2' 1'Type of Spillway Construction STONE WITH FLASH BOARDSType of Dike Construction EARTH & STONE1880? Downstream Conditions R/E "191 40' DOWN STREAMSummary of File Data CHECK FILE ON THIS DAM AND FILERemarks THIS OLD DAM IS IN POOR CONDITION  
HAS 2 FLASH BOARDS ON TOP WHICH SHOULD BE REPAIRED  
OR REMOVED. REPAIR MEMBERS SHOULD INSPECT THIS  
DAM. AS IT APPEARS TO BE IN NEED OF REPAIRSTELL - CHECK FILE ON THIS BEFORE DECISION  
MADE

# BUCK & BUCK

ENGINEERS

650 MAIN STREET HARTFORD 3, CONNECTICUT

HENRY WOLCOTT BUCK  
ROBINSON D. BUCK

COMM. 5574-1

DECEMBER 19, 1955

STATE BOARD FOR SUPERVISION OF DAMS  
165 CAPITOL AVENUE  
HARTFORD, CONNECTICUT


GENTLEMEN:

WE ARE WRITING ON BEHALF OF OUR CLIENTS  
CHARLES E. PRESSLER, JR. AND ROBERT J. PIGEON, OWNERS  
OF THE BUILDING IN THE CENTER OF THE VILLAGE OF BROAD  
BROOK ON THE WEST SIDE OF MAIN STREET, IMMEDIATELY NORTH  
OF BROAD BROOK, ACTING THROUGH THEIR ATTORNEYS, PIGEON  
AND KAHAN, OF ROCKVILLE, CONNECTICUT.

THIS BUILDING WAS SEVERELY DAMAGED AT THE TIME OF  
THE FLOOD LAST AUGUST AND OUR CLIENTS WISH TO PETITION YOUR  
BOARD FOR AN INSPECTION OF THE DAM AT BROAD BROOK POND IN  
ACCORDANCE WITH SECTION 4730 OF THE GENERAL STATUTES. OUR  
PETITION RELATES TO THE CAPACITY OF THE SPILLWAY PROVIDED AT  
THIS STRUCTURE AND ITS EFFECT ON THE BREAKING AWAY OF THE EARTHEN  
PORTIONS OF THE DAM AND NOT TO THE STRUCTURAL ADEQUACY OF THE  
SPILLWAY SECTION OF THE DAM.

SINCERELY YOURS,

BUCK & BUCK

  
HENRY WOLCOTT BUCK

RECEIVED  
DEC 20 1955  
STATE WATER COMMISSION



STATE OF CONNECTICUT  
STATE BOARD FOR THE SUPERVISION OF DAMS  
317 STATE OFFICE BUILDING, HARTFORD 15

RECEIVED

JAN 13 1956

STATE WATER COMMISSION

January 12, 1956

Re: Broad Brook Pond Dam  
East Windsor, Connecticut

Mr. William S. Wise  
Chairman, State Water Commission  
Hartford, Connecticut

Dear Sir:-

On last Saturday I visited the dam at Broad Brook just above the main road in the Village of Broad Brook and Town of East Windsor.

The dam is located just east of the highway and is a stone masonry dam about 84 feet long and is about 12 feet high. There appear to be wooden flashboards above the masonry for a depth of about 3 feet. The height from top of flashboards to top of abutment wall is 3 feet also. There is a stone wall along the south side of pond at about the 3 foot height and along the west side of pond is a stone wall and further on an earthen embankment. I do not know if this bank was overtopped in the recent floods but I suspect it was. There is a pond of perhaps 10 acres at this point.

The drainage area at the point of dam on Broad Brook is 14.8 square miles. The length of main stream is 6.5 miles. Branches are small and although included in drainage area are not considered separately in general stream slope. The elevation at source of stream is 600 and at dam is about Elevation 100 giving a slope of 500 feet in 6.5 miles or an average slope of 77 feet per mile. There does not appear to be any abnormal storage along the stream.

The mean annual flood then becomes

$$\begin{aligned}Q_m &= 0.85 A S \\Q_m &= 0.85 \times 14.8 \times 77 \\&= 968 \text{ cubic feet per second}\end{aligned}$$

A flood of 100 year frequency equals 3.7 times the mean annual

$$\begin{aligned}\therefore Q &= 3.7 \times 968 \\&= 3580 \text{ cubic feet per second for 100 year frequency.}\end{aligned}$$

Present dam is 84 feet long and 3 feet high to abutments from top of flashboards. This is good for 1478 cubic feet per second.

Conclusion:

It is my opinion that the present spillway capacity is wholly inadequate for a 100 year flood. If all flashboards were removed to the masonry top, then an adequate capacity would be provided.

Very truly yours,

*B. H. Palmer.*

BHP/ew

## STATE BOARD OF SUPERVISION OF DAMS

## APPLICATION FOR CONSTRUCTION PERMIT

As required under Section 4731 of General Statutes



THIS APPLICATION TO BE SUBMITTED IN TRIPLICATE

Hamilton Standard Division  
United Aircraft Corp.Date June 22, 1956Owner e/o John J. MozzochiTel. No. Madford 3-9401P. O. Address 265 H. Bron AvenueGlastonbury, Connecticut



## Location of Structure:

Town Broad BrookShown on USGS Quadrangle Broad BrookName of Stream Broad Brookat 5.8 inches south of Lat. 41°-52'-30"  
northabd 1.75 inches east of Long. 72°-30'  
westDirections for reaching site from nearest village or route intersection:  
(See sketch on reverse side)Dam is at the intersection of Connecticut Rt. No. 140 (Main Street) andDepot Street in the center of Broad Brook.This is an application for: (New Construction) (Alteration) (Repair) (Removal)  
(describe project)This pond is to be used for: Manufacturing and recreationDimensions of pond: width 500' AV. length 2000' ± area 25 ± AcresDepth of water below spillway level: Varies -- 10' Max.Total length of dam: 110'Length of spillway: 80'Height of abutments above spillway: 5.8'Type of spillway construction: Masonry with flash boardsType of dyke construction: Masonry and earthCharacter of soil in river bed at spillway location: LedgeRemarks: Proposed work involves rebuilding flashboards and other repairs.See attached Plans.Note: Show details of  
construction on reverse side.Signed John J. Mozzochi

FOR: HAMILTON STANDARD



MAIN STREET PLAN



ELEVATION

REMOVE APRON TO ELEV. 80' OR 6" ABOVE TOP OF TWIN 14" R.C. PIPES


# MILL POND DAM

PROPERTY OF  
HAMILTON STANDARD DIVISION  
UNITED AIRCRAFT CORPORATION  
BROAD BROOK, CONN.

JOHN J. MOZZOCHI, ENGINEER  
GLASTONBURY, CONN.

SCALE—NOT TO SCALE DATE—6-22-1955  
ELEV. DATUM: U.S.C. & G.S. APPROX.

5-56-63



JJM

DATE PREPARED

6/21/56

JOHN J. MOZZOCHI

Civil Engineer  
Glastonbury, Conn.

COMPUTATION SHEET

ORGANIZATION (or UNIT) NO.

WORK ORDER NO.

56-63

SHEET NO.

2 of 4

SUBJECT: MILL POND DAM, BROAD BROOK CONN.

$$\begin{aligned} \text{DISCHARGE } Q &= C_B H S \\ &= (0.85)(13.60)(30) \end{aligned}$$

$$Q_{\text{NORMAL}} = 348 \text{ CFS}$$

$$Q_{100} = 3.7 \times 348 = 1286 \text{ CFS}$$

CAPACITY CALCULATIONS (WITH FLOW 1'-0" ABOVE FLASHBOARD: OR ELEV 87

① 2 SLUICE GATES - EACH 24"X90" - BOTH OPEN

$$\begin{aligned} Q &= 2 \times C A \sqrt{2gh} \\ &= 2 \times 0.70 \times 9.4 \times \sqrt{2(32.2)(5.2)} = 240 \text{ CFS.} \end{aligned}$$

SPILLWAY - WITH BOARDS IN PLACE

$$\begin{aligned} Q &= C L H^{3/2} \\ &= 3.33 \times 80 \times 1^{3/2} = 267 \text{ CFS} \end{aligned}$$

TOTAL 507 CFS

$$\frac{507}{348} = 1.46 - \text{EQUAL TO 8 YEAR RECURRENCE}$$

WITH FLOW AT 2' ABOVE FLASHBOARDS OR ELEV. 88

② 2 SLUICE GATES

$$Q = 2 \times 0.70 \times 9.4 \sqrt{2(32.2)(6.2)} = 263$$

SPILLWAY - WITH BOARDS IN PLACE

$$Q = 3.33 \times 80.0 \times (2)^{3/2} = 755$$

1018 CFS

$$\frac{1018}{348} = 2.93 \text{ EQUAL TO 50 YEAR RECURRENCE}$$

WITH FLOW AT 3' ABOVE FLASHBOARDS OR ELEV. 89

③ 2 SLUICE GATES

$$Q = 2 \times 0.70 \times 9.4 \sqrt{2(32.2)(7.2)} = 284 \quad 284$$

SPILLWAY WITH BOARDS IN PLACE

$$Q = 3.33 \times 80.0 \times (3)^{3/2} = 1385$$

1669 CFS

④ SPILLWAY WITHOUT FLASHBOARDS

$$Q = 3.33 \times 80.0 \times (4.75)^{3/2} = 2780$$

3064 CFS

$$\text{RECURRENCE INTERVAL FOR } ③ - \frac{1669}{348} = 4.9 = 275 \text{ YEARS}$$

$$\text{" " " } ④ - \frac{3064}{348} = 8.8 = 800 \text{ YEARS (ESTIMATED)}$$



JOHN J. MOZZOCHI  
CONSULTING ENGINEER  
GLASTONBURY • CONNECTICUT

## SPECIFICATIONS

FOR

REPAIRS TO

MILL POND DAM

BROAD BROOK, CONNECTICUT

SCOPE

The work involved consists of:

- (1) Replacing the existing flashboards with new boards constructed as shown in detail on Sheet No. 1. Re-use existing 1-1/4" Philippine Mahogany planks as may be salvaged. Replace balance as needed with same material. Reset the existing sill on the northerly half of the Dam. Provide wrought iron anchors for the braces and new 2" oak splash boards.
- (2) Removing entirely the masonry retaining wall and embankment between the sluice gate channel and the retaining wall at Depot Street.
- (3) Material available from operation (2) is to be used to raise the earth dike East of Hall & Mass. Gas Station.
- (4) Remove the existing trash rack and rebuild same entirely of wrought iron frame and slats in a new location, just ahead of the sluice gates. Overall size of new rack to be same as existing.

**JOHN J. MOZZOCHI**  
CONSULTING ENGINEER  
GLASTONBURY • CONNECTICUT

MILL POND DAM

- (1) Repair the sluice gates as needed with about 20 S.F. each of new 2" Oak plank, dressed on both (4) sides, and a new 4" x 6" x 14'-0" Oak gate shaft. Planks and partition are bolted to gate shaft. Each gate has 2 - 1/2"  $\phi$  tie rods.
- (2) Remove the masonry portion of the sluice gate apron to a level 6" above top of 12" 14" R.C. pipes.
- (3) Repair all masonry joints as needed.

NOTE

All repair operations are to be completed in a manner at times consistent with the need of supplying the full water requirements of the Plant.

All work shall be of the best workmanship and all material of the best commercial quality. All debris shall be removed from the site. New embankment at rear of Gas Station shall be graded in a neat manner.

June 29, 1956

Mr. John J. Mozzochi  
265 Mebron Avenue  
Glastonbury, Connecticut

Dear John:-

I enclose preliminary permit for repairs to the flashboards at the dam at Broad Brook, Connecticut. The capacity of this dam is adequate provided the flashboards go under high floods and I should think that they would under the type of construction which you have indicated. The final permit will be issued after the work has been completed.

Very truly yours,

*B. H. Palmer*

Member, State Board of Supervision of Dams

DJP/cw

C.C.: Chairman Wm. S. Wise

STATE OF CONNECTICUT

BOARD OF SUPERVISION OF DAMS

3- 31

PRELIMINARY PERMIT

To Owner UNITED AIRCRAFT CORP

P. O. Address HARTFORD CONN.

NORWICH....., Conn.  
JUNE 29....., 19 56

I have inspected the site and have examined the plans marked MILL POND DAM


and the specifications therefore, submitted by you to the Board of Supervision of dams for .....

REPAIRS TO FLASH BOARDS

on BROAD BROOK..... in the Town of EAST WINDSOR.....

The same are approved, and such proposed construction work is hereby authorized.

*Benjamin H. Palmer*  
Member, Board of Supervision of Dams



STATE OF CONNECTICUT  
STATE BOARD FOR THE SUPERVISION OF DAMS  
STATE OFFICE BUILDING • HARTFORD 15, CONNECTICUT

December 3, 1956

Mr. William S. Wise  
Chairman, State Board for Supervision of Dams  
Hartford (15) Connecticut

Dear Mr. Wise:-

I enclose copy of Preliminary and  
Final certificates granted to United Aircraft Corporation  
for work on the dam at East Windsor.

Very truly yours,

*B. H. Palmer*

Member, State Board for Supervision of Dams

BHP/ew  
Enc.

STATE OF CONNECTICUT  
BOARD OF SUPERVISION OF DAMS

3- 31

CERTIFICATE OF APPROVAL

To Owner *United Aircraft Corp*  
P. O. Address *Hartford Conn*  
Name of Structure .....

*New Britain*, Conn.  
*Oct 1*, 1956

This is to certify that the following construction work: *Repairs to flash boards*  
....., performed on property owned by you on  
*Broad Brook*....., in the Town of *East Windsor*  
for which preliminary permit was issued *June 29 1956* has been completed to the satisfaction  
of this Board and that such structure is approved and has been found to be safe as of date of this certificate.

BOARD OF SUPERVISION OF DAMS  
BY

*Benjamin H. Palmer*....., Member

Note: The owner is required by law to record this certificate in the Land Records of the town or towns in which the dam  
is located.

March 20, 1963

Mr. A. J. Macchi  
44 Gillett Street  
Hartford, Connecticut

Dear Mr. Macchi:

Under your terms as a consultant to this office would you kindly inspect the following dams: Broad Brook, Mill Pond, dam on Chestnut Brook and Windsorville Pond in the Town of East Windsor and submit a report to this office as to present condition of the above named structures. Also include in your report the action this Commission is to take in each of the above mentioned dams.

Very truly yours,

Emitt A. Dell  
Field Inspector

EAD:js

DAM AT BROAD BROOK MILL POND  
TOWN OF EAST WINDSOR  
REPORT OF INSPECTION BY A. J. MACCHI, ENGINEERS  
ON MARCH 22, 1963

---

This dam is located on Broad Brook west of the Main Street in Broad Brook Center. The dam consists of a vertical stone wall with earth fill backup. The watershed area is approximately 9,000 acres and extends east to an area above the town of Rockville. There are numerous residences and manufacturing plants below the dam site. The dam is owned by Hamilton Standard, Division of United Aircraft.

Water elevation is controlled by wooden flashboards which have been designed to fail before the water elevation becomes critical and tops the embankment adjacent to the dam. Our review of this design indicates that in this type of flashboard, which is intended to fail by rotation of the unit about a horizontal axis when the design head has been reached, the location of the axis of rotation and the detail at this hinge is very critical. Inasmuch as it is the design objective that these flashboards fail before the critical elevation is reached, which would flood adjacent buildings, it is recommended that the design of these units be reviewed and modified if necessary in order to be positive about their function.

*Buck*      *2*  
              *13 INVESTIGATING*  
              *5-17-63*

STATE WATER RESOURCES COMMISSION	
RECEIVED	
APR 3 1963	
ANSWERED.....	
REFERRED.....	
FILED.....	

*Sub. 100-100*  
**A. J. M A C C H I**

**E N G I N E E R S**

**DR. GIULIO PIZZETTI**

**ASSOCIATE CONSULTANT**

44 GILLETT STREET  
17 CORSO DUCA ABRUZZI

HARTFORD, CONN.  
TORINO, ITALY

PHONE 525-6631  
PHONE 519-473


N.S.P.E.

A.S.C.E.

A.C.I.

April 18, 1963

Water Resources Commission  
State of Connecticut  
165 Capitol Avenue  
Hartford, Connecticut



Re: Dam at Broad Brook Mill Pond


Gentlemen:

Reference is made to our report of inspection at the above dam on March 22, 1963, wherein we recommended that the design of the flash boards be reviewed.

Please be advised that this office has corresponded with John J. Mozzochi, Engineers for Hamilton Standard, owners of this dam, and they intend to revise the flashboards in a manner acceptable to this office.


Very truly yours,

A. J. MACCHI, ENGINEERS

  
H. R. HOFFMAN, P. E.

cc. John J. Mozzochi & Associates

**TOWN OF EAST WINDSOR**  
**CONNECTICUT**



BOARD OF SELECTMEN  
P. O. Box 366  
BROAD BROOK, CONNECTICUT

June 1, 1966

State of Connecticut  
Water Resources Commission  
State Office Building  
Hartford 15, Connecticut

Dear Sir:

Hamilton Standard, Division of United Aircraft Corporation has offered the Town of East Windsor a gift of the Broad Brook Pond and some land surrounding it.

This offer was presented before a Special Town Meeting on May 26, 1966 and the vote was to accept the offer with two provisions:

1. That the towns insurance carrier would insure the area against any and all liability.
2. That the Board of Selectmen obtain a favorable written report from the State Water Resources on the condition of the dam.

I am therefore asking the Commission for a report on the dam's condition.

(Very Truly yours,  
*John L. Daly Jr.*  
John L. Daly Jr.  
First Selectman



# A. J. M A C C H I • E N G I N E E R S

EXECUTIVE OFFICES • 44 GILLETT STREET • HARTFORD, CONN., 06105 • PHONE 525-6631

A. J. MACCHI  
H. R. HOFFMAN  
K. E. GRIFFES  
J. J. SCHMID


ASSOCIATE CONSULTANT  
PROF. C. W. DUNHAM

June 22, 1966

State of Connecticut  
Water Resources Commission  
165 Capitol Avenue  
Hartford, Connecticut

Attention Mr. William Sander

Re: Your Letter 6/17/66  
Broad Brook Dam  
Broad Brook, Connecticut



Gentlemen:

Inspected the above-referenced dam on Tuesday, June 21, 1966. This dam was previously reviewed on March 22, 1963.

In our previous report we asked for a modification of the flashboard detail which is designed to fail safe. The requested changes have been made.

The flashboards need clearing of debris at the present time and periodically this should be done to allow free movement of the flashboards. The growth of small saplings at the south abutment should be removed.

The dam is in safe condition.

Very truly yours,

A. J. MACCHI, ENGINEERS

A. J. MACCHI

A large, stylized handwritten signature in dark ink, appearing to read "A. J. Macchi", is written over the typed name "A. J. MACCHI".

*Copy given me by memo, firm*  
**HAMILTON STANDARD**

Windsor Locks, Connecticut 06096

Please address answer to  
Mail Stop No. 2-M-1

March 29, 1976

Mr. Edward Hastillo  
First Selectman  
Town of East Windsor  
Town Hall  
Broad Brook, Connecticut 06016

Dear Mr. Hastillo:


We have had two occasions of significant property damage at our Broad Brook facility caused by a failure to relieve the water pressure at the dam during heavy flooding conditions, and the resultant failure of the top rails. In each case, the damage has exceeded \$2,500. The situation is further aggravated since it takes a long time to have the town replace those top rails. As a result, we operate with limited water flow. I hope you can expedite the repair of the dam.

We also expect that in future flooding conditions the town will take whatever action is necessary to relieve the pressure on the top rails to prevent resulting downstream damage to private property. This letter constitutes notice that should the Town of East Windsor not take necessary corrective action to ensure that no further damage is caused to the property of Hamilton Standard, we will expect the Town to be liable for and pay the cost of any further damage.

We request that you advise us as soon as possible of the corrective action you propose to take to alleviate the problem.


Very truly yours,

HAMILTON STANDARD  
Division of UTC



Richard Ryan  
Plant Engineer

RR:ekb



COPY



# STATE OF CONNECTICUT

DEPARTMENT OF ENVIRONMENTAL PROTECTION

STATE OFFICE BUILDING

HARTFORD, CONNECTICUT 06115

COPY

12 April 1976

Mr. John Macchi  
Macchi Engineers  
44 Gillett Street  
Hartford, CT

Re: Broad Brook Millpond  
East Windsor

Dear John:

Under the terms of your contract to act as a consultant to this department, would you please inspect the subject dam and submit a report on the safety of the dam.

The dam is located in Broad Brook in the northeast section of East Windsor east of Route 191.

Very truly yours,

Victor F. Galgowski  
Supt. of Dam Maintenance  
Water Resources Unit  
Telephone no. 566-7245

VFG:ljg

BROAD BROOK MILL POND

EAST WINDSOR, CONNECTICUT

REPORT ON CONDITION OF DAM AND  
FACTORS RELATIVE TO ITS USE

BY MACCHI ENGINEERS, HARTFORD, CONN.

MAY 4, 1976

---

LOCATION - Dam is located on Broad Brook just east of Main Street bridge in East Windsor, Connecticut.

DESCRIPTION - This dam is a stone masonry wall approximately 8'-3" high, setting on bedrock. It is topped with a heavy wood sill and flashboards about 1'-10" high having an overall length of about 96' which form the spillway. See attached sketch, revised to date.

OWNER - Town of East Windsor.

CONDITION - The dam is a safe structure in good condition and in no danger of failure. The critical factor is how best to allow passage of flood flows with a minimum of exposure by erosion of the downstream banks, a distance of about a mile to the confluence with the Scantic River. The hinged flashboards which are used to raise the pond level overturn on flood flows and contribute to the erosion.

HYDRAULICS - The drainage area above this dam is about 9,062 acres and the flood flows using Connecticut Flood flow formula are calculated to be:

Annual Flood.....	1,000 c.f.s.
5 Yr. Flood.....	1,300 c.f.s.
10 Yr. Flood.....	1,600 c.f.s.
100 Yr. Flood.....	3,700 c.f.s.
200 Yr. Flood.....	5,000 c.f.s.

Mozzochi Engineer's sketch dated 6/22/56 indicates a pond elevation of 89.4 for the 1955 flood. Assuming flashboards were washed out, the flow estimates to be approximately 4,300 c.f.s., a 200 year flood.

Since 1961, a U.S.G.S. gaging station has been located approximately 2000 ft. downstream at the Mill Street crossing.

The following peak flow data was made available by Mendal Thomas of the U.S.G.S. office in Hartford:

2/3/70.....	800 c.f.s.
3/3/72.....	800 c.f.s.
6/30/73.....	708 c.f.s.
9/27/75.....	1140 c.f.s.

The September 27, 1975 peak flow of 1140 c.f.s. coincided with a 24 hr. precipitation of 3.07" at nearby Bradley Airport during the previous day.

The October 19, 1975 washout of flashboards occurred during a 3 day rainstorm with precipitation of less than 1.5"/24 hrs.

The February 1976 rainfall conditions were less severe.

HISTORY - Hamilton Standard is the previous owner of the dam and within the last few years turned over ownership of the dam to the Town of East Windsor. Hamilton Standard still uses the water from the mill pond for processing in the nearby plant and maintains a weir downstream to take water for fire protection.

We were informed by local residents and Mr. Ray Morris, Assistant Plant Manager and Harry Ishler, local plant maintenance, both of Hamilton Standard, that flashboards have washed out twice within the last year; once in October, 1975 and in February, 1976. On both occasions we were told the water level in the pond was only slightly above the top of the flashboards. Checking precipitation records for both these times, we find there was insufficient rain to cause flashboards to fail by overturning as per design. Most likely, the flashboards failed because the struts were inadequate.

On these occasions when the flashboards failed, Mr. Morris claims scour damage occurred to an area downstream adjacent to the brook where large tanks are located. He stated that when Hamilton Standard maintained the dam they relieved the pond build up by opening the two sluice gates at the start of a storm and this practice prevented flashboards from washing out. This practice has not been continued since the Town has taken over the dam. About one-half of the flashboards washed out. We estimate this discharge to be comparable to annual flood of about 1000 c.f.s.

FINDINGS & RECOMMENDATIONS - The location of the flashboard hinge is a sensitive and critical factor in establishing the height of water above the weir required to cause overturning. We learned that this hinge point as related to total height of the flashboards was changed from dimensions obtained from 1963 records. We waited for a low flow day to verify actual measurements. From this information it was determined that the height required to overturn the flashboards is approximately 2 ft. During the recent failure of the flashboards the water did not reach this 2' height and therefore, the bracing system must have given way.

In checking the channel of this brook from the dam to where it flows into the Scantic River, a distance of about a mile, we find that this water course is very meandering and restrictive, and that some erosion of banks by a large flood flow is unavoidable, especially where the channel changes direction. It is recommended that property adjacent to the edge of the brook not be used for permanent installations unless banks are protected. A sudden release of a wave of water when flashboards let go can be very destructive to the banks. Whereas, if the flashboards remain in place, the flood flow will be more gradual and over a longer period of time.

All flood flows are normal (natural) exposures to adjacent property. However, sudden discharges which exceed unrestricted conditions are open to questionable liability.


It is recommended that flashboards be fixed in place (cut down 6" from present height to elevation 85.5) and that sluice gates be opened at the beginning of anticipated heavy storms. The fire company across the street could assume this responsibility for the Town. These sluice gates can be made automatic by use of float switches and electric motor, if so desired.

This operation will allow passage of 100 year storm without overflowing banks. Storms greater than this will wash over adjacent parking area and possibly across the road.


If the elevation of 86.0 (the present top of the flashboards) must be maintained, then it will be necessary to increase the banks to maintain a 6" freeboard along the shores of the pond.


To make flashboards permanent, the braces (struts) for the flashboards should be made stronger using a second 2 x 4 brace near the top of the vertical member. The flashboards should then be inspected annually and after every heavy flood flow.

MACCHI ENGINEERS





A. J. MACCHI, P.E.





MAIN STREET PLAN



ELEVATION

# MILL POND DAM


PROPERTY OF  
HAMILTON STANDARD DIVISION  
UNITED AIRCRAFT CORPORATION  
BROAD BROOK, CONN.

JOHN J. MOZZOCHI, ENGINEER  
GLASTONBURY, CONN.

SCALE - NOT TO SCALE DATE 6-22-1956  
ELEV. DATUM U.S.C. 16.3 APPROX.


INFORMATION AND IN APP. 15, 74





PLAN VIEW  
E. A. L. POND DAM  
SCALE 1" = 10'

MAIN ST



SECTION A-A

SCALE 1" = 10'



DESIGNED BY  
E. A. L. POND DAM  
MILL POND DAM  
E. A. L. POND DAM

**E. A. L. POND DAM**



CONSULTING ENGINEER

VERNON

DATE

BY





CT-00271

Broad Brook Mill Pond Dam

